

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 0:00 on October 18,)**

Water Level of the accumulated water (at 0:00 on October 18)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 917 mm (No change since 0:00 on October 17)	T.P.+ 805 mm (8 mm increase since 0:00 on October 17)	T.P.+ 921 mm (4 mm increase since 0:00 on October 17)
	Water level of Reactor Building	T.P.+ 908 mm (39 mm decrease since 0:00 on October 17)	T.P.+ 968 mm (33 mm increase since 0:00 on October 17)	T.P.+ 842 mm (7 mm increase since 0:00 on October 17)	T.P.+ 805 mm (2 mm increase since 0:00 on October 17)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ -737 mm (18 mm decrease since 0:00 on October 17) T.P.+ 936 mm (1 mm increase since 0:00 on October 17) T.P.+ 2,894 mm (32 mm increase since 0:00 on October 17)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.