

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 0:00 on November 22,)**

Water Level of the accumulated water (at 0:00 on November 22)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 926 mm (No change since 0:00 on November 21)	T.P.+ 765 mm (10 mm decrease since 0:00 on November 21)	T.P.+ 912 mm (3 mm increase since 0:00 on November 21)
	Water level of Reactor Building	T.P.+ 793 mm (4 mm increase since 0:00 on November 21)	T.P.+ 956 mm (5 mm decrease since 0:00 on November 21)	T.P.+ 798 mm (3 mm decrease since 0:00 on November 21)	T.P.+ 778 mm (No change since 0:00 on November 21)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 772 mm (40 mm increase since 0:00 on November 21) T.P.+ 1,155 mm (1 mm increase since 0:00 on November 21) T.P.+ 2,816 mm (13 mm increase since 0:00 on November 21)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.