

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 0:00 on December 26,)**

Water Level of the accumulated water (at 0:00 on December 26)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 401 mm (5 mm increase since 0:00 on December 25)	T.P.+ 361 mm (14 mm decrease since 0:00 on December 25)	T.P.+ 452 mm (20 mm increase since 0:00 on December 25)
	Water level of Reactor Building	T.P.+ 426 mm (No change since 0:00 on December 25)	T.P.+ 454 mm (10 mm decrease since 0:00 on December 25)	T.P.+ 429 mm (5 mm decrease since 0:00 on December 25)	T.P.+ 552 mm (4 mm decrease since 0:00 on December 25)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 795 mm (26 mm decrease since 0:00 on December 25) T.P.+ 913 mm (No change since 0:00 on December 25) T.P.+ 2,752 mm (12 mm increase since 0:00 on December 25)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.