

**Situation of water level, transfer and treatment of the accumulated water  
in Fukushima Daiichi Nuclear Power Station (at 0:00 on January 19,)**

Water Level of the accumulated water (at 0:00 on January 19)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 399 mm (No change since 0:00 on January 18)	T.P.+ 362 mm (4 mm decrease since 0:00 on January 18)	T.P.+ 424 mm (9 mm increase since 0:00 on January 18)
	Water level of Reactor Building	T.P.+ 406 mm (27 mm decrease since 0:00 on January 18)	T.P.+ 456 mm (16 mm increase since 0:00 on January 18)	T.P.+ 464 mm (3 mm decrease since 0:00 on January 18)	T.P.+ 396 mm (3 mm decrease since 0:00 on January 18)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 2,693 mm (75 mm decrease since 0:00 on January 18) T.P.+ 980 mm ( No change since 0:00 on January 18) T.P.+ 3,080 mm (16 mm increase since 0:00 on January 18)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.