Fukushima Daiichi Nuclear Power Station: Strontium analysis result in the air

- 1. Sampling spot: West gate of Fukushima Daiichi Nuclear Power Station
- 2. Analyses organization: Japan Chemical Analysis Center
- 3. Analysis result:

(Unit: mBq/m³)

Type of sampling	Date of	Sr-89	Sr-90
	sampling		
Volatile	May 9	N.D.	N.D.
Particle		N.D.	N.D.

4. Evaluation:

Sr-89 and Sr-90 were not detected from the sample analyzed this time.

END