

Pu analysis result in the seawater at Fukushima Daiichi Nuclear Power Plant

1. Sampling points : Fukushima Daiichi Nuclear Power Plant , North water intake canal of Units 1-4
2. Analysis Institute: Japan Chemical Analysis Center
3. Results :

(Unit: mBq/L)

Sampling Point	Date	Pu-238	Pu-239,Pu-240
North water intake canal of Units 1-4	10/10	N.D. [$<5.4 \times 10^{-1}$]	N.D. [$<5.9 \times 10^{-1}$]

[]:measurable limit

4. Evaluation:

No Pu-238,Pu-239,Pu-240 were detected.

END