

(Reference) Partial collapse of slopes on site

① Near the mouth of the Jimbazawa River

【Location of collapse】



【Partial collapse of slope】



② Daini spoil bank north site access road

【 Location of collapse 】



【Partial collapse of slope】



【After emergency repairs】

